




QD-U11A

UNIVERSAL A/C CONTROL SYSTEM



UNIVERSAL A/C
CONTROL SYSTEM

QD-U11A



1 There should be no strong light before the IR (infra red light receiver).
2 For split A.C., the stepper motor socket (MOTOR) has 6 pins. Two pins on both sides are common pins (12V). Either of them must be connect with the common pin of the stepper motor plug that has 5 pins. If stepper motor rotating direction is reversed, the common pin of the motor plug should be connect to be other common pin of the motor socket.


CE MADE IN CHINA

QD-U11A
UNIVERSAL A/C
CONTROL SYSTEM



QD-U11A
UNIVERSAL A/C CONTROL SYSTEM

UNIVERSAL A/C CONTROL SYSTEM QD-U11A



- 5 Working Mode
- 3 Fan Speed
- 2 Sensors
- Digital LED Display
- Prevent Cold Wind in Heating Mode
- Auto Restart Function
- Main Board With Base Holder

QD-U11A

UNIVERSAL A/C CONTROL SYSTEM

! Please install by certificated technician.
Please test the system before installation.
Please avoid strong light before IR receiver